

WH0100 Wireless In/Out Thermometer with Humidity



Features:

- 1) Indoor temperature (°C or °F)
- 2) Remote temperature (°C or °F)
- 3) Remote humidity
- 4) One WH2 transmitter included
- 5) Free standing or wall mount
- 6) Minimum and maximum memory
- 7) Low power consumption (approx. 2 years battery life)

Specifications:

- 1) Humidity range: 20% - 95% (+/-5% under 0 to 45°C)
- 2) Remote temperature range: -40 ~ +65°C
- 3) Indoor temperature range: 0 ~ +60°C
- 4) Temperature accuracy: +/-1.0°C
- 5) Transmission frequency: 433MHz
- 6) Transmission range: up to 100m line of sight

Power requirements:

- Base station: 2 x "AA" alkaline batteries (not included)
Sensor : 2 x "AAA" alkaline batteries (not included)

Dimensions:

- Base station: 113 x 67 x 27.5mm
Sensor : 91 x 70 x 32.5mm